

Huawei PCN AR G3 -20120002 Change Notice of Captive Screws on AR G3 Enterprise Router Filler Panels

0. Abstract

The captive screws on AR1200/AR2200/AR3200 enterprise router filler panels are changed to black countersunk head crews, and product functions remain unchanged. The change notice is intended for the customers who purchased Huawei AR1200, AR2200, and AR3200 series.

1. Vendor

Huawei Technologies Co., Ltd.

2. PCN Information

PCN No.		AR G3 -20120002	
PCN Version		Rev: 01	
PCN Type		D	
Roadmap	Release date	2012-6-30	
	Implementation date	2012-12-31	

3. Affected Systems and Products

3.1 Hardware Change

Category	Product	Hardware	Software	Firmware	Plug-In
AR G3	AR1200, AR2200, and AR3200 series enterprise	Yes	No	No	No

	routers				
--	---------	--	--	--	--

4. Other Changes

None.

5. Part Number Change

None.

6. Change Reason

To make the appearance nicer, change the captive screws on AR1200/AR2200/AR3200 enterprise router filler panels to black countersunk head crews.

7. Change Description

The captive screws on AR1200/AR2200/AR3200 enterprise router filler panels are changed to black countersunk head crews, and product functions remain unchanged. This change involves AR0M0012BA00, AR0MNTEH10100, AR0MNTEH10201, AR0MNTEH10301, AR0M012BBA00, AR0M012VBA00, AR0M0022BA00, AR0M0022BD00, AR0MNTEH10401, AR0M0024BA00, AR0M0024DC00, AR0M0024ED00, AR0M0024EA00, AR0M0036BA00, AR0M0036BD00, AR0MNTEH10501, AR0M0036SA00, AR0M0036SD00, AR0M012SBA00, AR0M012WBA00, AR0M12WSBA00, AR0M12VWBA00, AR0M1200CC00, AR0M022SBA00, and AR0M2200CC00.

8. Impact


Security	Fire Proof	Service	Communications
None	None	None	None
Maintenance	Reliability	Power Supply/Power Consumption	Traffic Volume
None	None	None	None

9. Affected Documents

None.


10. Image

- The following figures show the change of captive screws on AR1200/AR2200/AR3200 filler panels.



This change involves the following AR models:

- On the AR1220, the captive screws on filler panels of two SIC card slots are changed.



- On the AR2220, the captive screws on filler panels of four SIC card slots and two WSIC card slots are changed.



- On the AR2240, the captive screws on all filler panels of interfaces and the filler panel of one XSIC card slot next to the main control board are changed.



- On the AR3260, the captive screws on all filler panels of interfaces and the filler panels of three XSIC card slots next to the main control board are changed.



11. Remarks

If you have any questions about the change, contact Huawei sales representatives or technical personnel.